



SECTION A-A



SECTION B-B



Ensure that,

- 1) The molding compound is polystyrene (shrinkage approx 0.5%)
- 2) There are no burrs on the product (molded part).
- 3) There are no cutter marks of machining on the surface of the product (molded part).
- 4) There are no scratches, dents, etc on the surface of the product (molded part).
- 5) There are no defective moldings such as flow marks, weld lines, burns, etc.
- 6) From capital letter "A" to "J" represent product's main dimension.
- 7) From capital letter "A" to "G" represent product's secondary dimension.
- 8) From small letter "a" to "g" represent mould's main dimension.
- 9) From small letter "a" to "g" represent mould's secondary dimension.

Test Project for the 42 nd WorldSkills Competition in Leipzig, Germany 2013. Copyright © 2011 Worldskills International. All Rights Reserved.				
Skill: D1:Plastic Die Engineering		OR		
Scale: 1.5:1	Date:			
Drawn / Design by: INDIA		Drawing No:		
Description: TEST PROJECT 2		Rev:	Page:	